



ENVIRONMENTAL COMPLAINTS & LOCAL SERVICES
TOTAL RETENTION FACILITIES
TOTAL RETENTION FACILITIES with LAND APPLICATION
WASTEWATER BYPASS FORM

DEQ Facility ID: s30601 Facility Name: Pittsburg County Rural Wa County: Pittsburg

Report all Total Retention Facility and
Total Retention Facilities with Land Application
wastewater bypasses to
DEQ/ Environmental Complaints and Local Services
within **24 hours** at:

1-800-522-0206

Mail or Fax written report including copies of ANY test results
within **5 days** to:

**Department of Environmental Quality
Environmental Complaints and Local Services
P.O. Box 1677
Oklahoma City, OK 73101-1677
Fax No. (405) 702-6226**

DEQ notified: 03 07 2018 0908 ☒ AM ☐ PM Received by: ep
Month Day Year Time

Period of bypass: From 03 07 2018 0908 ☒ AM ☒ PM
To ☐ AM ☐ PM
Month Day Year Time

Type of Bypass: ☐ Pipe ☒ Lagoon/Basin ☐ Manhole ☐ Head Works ☐ Lift Station ☐ Irrigation

Strength of Bypass ☒ Raw ☐ Partially Treated ☐ Re-use (Category 4) Amount of Bypass: gpd

Type of samples taken: ☐ BOD ☐ TSS ☐ Fecal ☐ pH ☒ None ☐ Other:

Geographical location of bypass and receiving stream if appropriate: lagoon

Reason for bypass: rainwater

Steps taken to prevent recurrence:

Were fish or other wildlife affected as a result of the bypass? ☐ Yes ☒ No How?

Impact to receiving stream and /or surrounding areas: none

Steps taken to clean up or treat bypass:

Reported by: Lacy Allen Title: Superv

Signature: Date: 030718 Phone #:
Facility Representative

DEQ EPS USE ONLY:

Type of Contact: ☐ Phone or ☒ Site Visit Date: 3/20/18 Follow up Site Visit ☐ Date:

Geographical location of bypass and receiving stream if appropriate: Northwest corner of Northen most lagoon cell

Reason for bypass: I&I issues resulting in lose of freeboard in cells

Steps taken to prevent recurrence: Under CO for addressing capacity issues and I&I issues

Impact to receiving stream and/or surrounding areas: None

Steps taken to clean up or treat bypass: lime areas

Corrective action needed: Comply by date:

Reported information confirmed: ☒ Yes ☐ No If no, explain:

Comments: District was discharging from second cell by use of large pump. discharge was not reported.

Signature: jonathan schult ID #: 284572 Date: 3/20/18
ECLS Representative

OKC Central Office Use Only
BYPASS ID #